SHEET NO. DESCRIPTION


1. COVER SHEET, INDEX OF SHEETS
2. GENERAL DATA
3.-4. JEFFERSON STREET BRIDGE OVER THE ROCK RIVER
5. WHITMAN STREET BRIDGE OVER THE ROCK RIVER
6. 10TH AVENUE BRIDGE OVER KEITH CREEK
7. APPLEWOOD LANE BRIDGE OVER SPRING CREEK
8. BMO HARRIS BANK CENTER PEDESTRIAN BRIDGE OVER CHURCH STREET

FOR LIST OF STATE STANDARDS SEE SHEET 2

CITY OF ROCKFORD


F.A.U. SECTION COUNTY SHEETS NO. WINNEBAGO 8 1 FED. ROAD DIST. NO. ILLINOIS CONTRACT NO.

PLANS FOR PROPOSED BRIDGE REPAIRS









FULL SIZE PLANS HAVE BEEN PREPARED USING STANDARD ENGINEERING SCALES. REDUCED SIZED PLANS WILL NOT CONFORM TO STANDARD SCALES. IN MAKING MEASUREMENTS ON REDUCED PLANS, THE ABOVE SCALES MAY BE USED.

J.U.L.I.E.
JOINT UTILITY LOCATION INFORMATION FOR EXCAVATION
1-800-892-0123

 \circ



PROJECT ENGINEER: STEVEN L. SCHWARZ, S.E., P.E.
PROJECT MANAGER: ANDREW E. UNDERWAGER, S.E., P.E.



LOCATION MAP

PROJECT LOCATION
APPLEWOOD LANE
OVER SPRING CREEK

CITY OF ROCKFORD		
APPROVED .	(DATE)	
-	CITY OF ROCKFORD, CITY ENGINEER	

STRUCTURAL ENGINEER'S SIGN & SEAL	
	
Ston I School	HRGreen
STEVEN L. SCHWARZ, S.E., P.E.	CARY, ILLINOIS OF ILLINOIS
6/23/2022	SS STEVEN L. SCHWARZ COME ON THE OWNER OF THE OWNER OWN
DATE	CARY, /FR
11/30/2022	STEVEN L SONWARZ CONTROLL NO STEVEN L SONWAR
EXPIRES	The state of the s

GENERAL NOTES:

- 1. Unless noted in the project Specifications, the most recent version of the IDOT Standard Specifications for Road and Bridge Construction, including the most recent version of the Supplemental Specifications and Recurring Special Provisions shall govern execution of this project, including the General Requirements in Division 100.
- 2. Plan dimensions and details relative to existing structures have been taken from existing plans and are subject to nominal construction variations. It shall be the Contractor's responsibility to verify such dimensions and details in the field and make necessary approved adjustments prior to construction or ordering of materials. Such variations shall not be cause for additional compensation for a change in scope of the work, however, the Contractor will be paid for the quantity actually furnished at the unit price for the work.
- 3. Traffic Control will generally consist of Day Time Lane Closures utilizing the State Standards listed at right. The City expects a single lane in each direction to remain open to traffic at all times. Lane closures between 9:00 AM and 3:30 PM weekdays will be allowed.

SUMMARY OF QUANTITIES

ITEM		QUANTITY
Structural Repair of Concrete (Depth equal to or less than 5 in.)	Sq. Ft.	567
Structural Repair of Concrete (Depth greater than 5 in.)	Sq. Ft.	8
Traffic Control and Protection, Special	Lump Sum	3
Anchor Bolt Tightening	Lump Sum	1
Pedestrian Handrail, Special	Foot	96
Wingwall Repair, Special	Lump Sum	1
Silicone Bridge Joint Sealer	Foot	12
Cleaning and Painting Steel Bridge	Lump Sum	1
Containment and Disposal of Non-Lead Paint Cleaning Residues		1


LIST OF STATE STANDARDS

000001-08 STANDARD SYMBOLS, ABBREVIATIONS AND PATTERNS 701606-10 URBAN LANE CLOSURE, MULTILANE, 2W WITH MOUNTABLE MEDIAN

701901-08 TRAFFIC CONTROL DEVICES

HRG PROJECT NO.: 191880	NO.: 191880
HRG PROJ. CONTACT:	NTACT:
FILE NAME: 191	FILE NAME: 191880.16_Str_gen.dgn
PLOT DRIVER:	PLOT DRIVER: IL.pdf.color.pltcfg
PEN TABLE: plotiabel, tbi	ilotlabel,tbl

USER NAME - whood	DESIGNED - SLS	REVISED -
	CHECKED - SLS	REVISED -
PLOT SCALE =	DRAWN - WJH	REVISED -
PLOT DATE = 6/23/2022	CHECKED - AEU	REVISED -



<u>PLAN</u>





Typical Sidewalk Repair



Parapet Repair at Junction Box



<u>LEGEND</u>

Concrete Parapet Repair (Length (Ft) as noted on plan) Height is assumed to be 1.5'

Concrete Curb and Gutter Repair (Length (Ft) as noted on plan) Height is assumed to be 0.75'

Concrete Sidewalk Repair (Area (SF) as noted on plan) Note: Parapet and sidewalk repairs will paid for as Structural repair of Concrete (Depth equal to or less than 5 in.)

BILL OF MATERIAL

ITEM		TOTAL
(Depth equal to or less than 5 in.)		505
Traffic Control and Protection, Special	L. Sum	1

<u>Scope of Work</u> Sidewalk / Parapet Concrete Repairs



HRGreen.com ■Inols Professional Design Fir # 184-001322

USER NAME - whood	DESIGNED - SLS	REVISED -
	CHECKED - SLS	REVISED -
PLOT SCALE =	DRAWN - WJH	REVISED -
PLOT DATE = 6/23/2022	CHECKED - AEU	REVISED -

<u>PLAN</u>







Typical Curb Repair

Typical Upper Parapet Repair

Typical Concrete Parapet Repair




<u>LEGEND</u>

Concrete Parapet Repair (Length (Ft) as noted on plan) Height is assumed to be 1.5'

Concrete Curb and Gutter Repair (Length (Ft) as noted on plan) Height is assumed to be 0.75'

Concrete Sidewalk Repair (Area (SF) as noted on plan)



STRUCTURAL REPAIR OF CONCRETE (DEPTH EQUAL TO OR LESS THAN 5 in.) Parapet and sidewalk repairs will paid for as Structural repair of Concrete (Depth equal to or less than 5 in.)

<u>Scope of Work</u> Sidewalk / Parapet Concrete Repairs




HRGreen.com

USER NAME - whood	DESIGNED - SLS	REVISED -
	CHECKED - SLS	REVISED -
PLOT SCALE =	DRAWN - WJH	REVISED -
PLOT DATE = 6/23/2022	CHECKED - AEU	REVISED -


CITY	0F	ROCKFORD

JEFFERSON STREET BRIDGE OVER THE ROCK RIVER	F.A. RTE.	SEC
STRUCTURE NO. 101-6135	0525	91.0039
SHEET NO. 2 OF 2 SHEETS		



PLAN







Parapet Repair

BILL OF MATERIAL

ITEM	UNIT	TOTAL
Structural Repair of Concrete (Depth greater than 5 in.)	Sq. Ft.	5
Anchor Bolt Tightening	L. SUM	1
Traffic Control and Protection, Special	L. SUM	1

<u>Scope of Work</u> Parapet Concrete Repairs, Anchor Bolt Tightening

Note: Cost to supply stainless steel nuts and washers for the missing ones is included in the cost of Anchor Bolt Tightening.

HRGreen

HRGreen.com

<u>LEGEND</u>


Concrete Parapet Repair (Length (Ft) as noted on plan) Height is assumed to be 7"

USER NAME - whood	DESIGNED - SLS	REVISED -
	CHECKED - SLS	REVISED -
PLOT SCALE =	DRAWN - WJH	REVISED -
PLOT DATE = 6/23/2022	CHECKED - AEU	REVISED -
1201 0412 - 0/25/2022	GILORED - ALO	WE 412ED

CITY OF ROCKFORD

WHITMAN STREET BRIDGE OVER THE ROCK RIVER STRUCTURE NO. 101-6136 SHEET NO. 1 OF 1 SHEETS

F.A.	SECTION		COUNTY	TOTAL	SHEE	
RTE.				SHEETS	NO.	
0734	94-00444-00-BR		WINNEBAGO	8	5	
•			CONTRACT	NO.		
	ILLINOIS	FED. AI	D PROJECT			







Existing Fence - South Side



Existing Railing - North Side

- Removal and disposal of existing railing is included in the cost of Pedestrian Handrail, Special.
- See Special Provisions for additional information Locate new railing 5' from face of curb.

BILL OF MATERIAL

ITEM	UNIT	TOTAL
Structural Repair of Concrete (Depth equal to or less than 5 in.)	Sq. Ft.	49
Pedestrian Handrail, Special	Foot	96
Traffic Control and Protection, Special	L. SUM	1

WINNEBAGO 8

CONTRACT NO.

<u>Scope of Work</u> Concrete Repairs, Remove and Replace Railings

<u>LEGEND</u>

Concrete Sidewalk Repair (Area (SF) as noted on plan)




	USER NAME	-	whood
,			
	PLOT SCALE	=	
	PLOT DATE	=	6/23/2022

Typical Concrete Repair

USER NAME - whood	DESIGNED -	SLS	REVISED -
	CHECKED -	SLS	REVISED -
PLOT SCALE =	DRAWN -	WJH	REVISED -
PLOT DATE = 6/23/2022	CHECKED -	AEU	REVISED -

10th AVENUE BRIDGE OVER KEITH CREEK	F.A. RTE.	SECTIO	NC	
STRUCTURE NO. 101-6042	3256			
3111001011L NO. 101-0042				
CHEET NO. 1 OF 1 CHEETS		1		





- Notes: 1. Attach to side of south west culvert wall \pm 1'-0" down from bottom of top slab with 5/8" dia. Galvanized Expansion Anchors.
- 2. Adjust final height of bracket so 4x4 angle provides a clearance of 1/4" to the rotated southwestern wingwall.
- 3. See Special Provisions for additional information.

BILL OF MATERIAL

Wingwall Repair, Special L. St	IM 1	

Scope of Work Install wingwall repair bracket

HRGreen,


HRGreen.com

USER NAME - whood DESIGNED - SLS REVISED CHECKED - SLS REVISED DRAWN - WJH REVISED PLOT DATE = 6/23/2022 CHECKED - AEU REVISED

CITY OF ROCKFORD


APPLEWOOD LANE BRIDGE OVER SPRING CREEK WINGWALL REPAIR SHEET NO. 1 OF 1 SHEETS

COUNTY TOTAL SHEET NO.
WINNEBAGO 8 7 SECTION CONTRACT NO.



- Structural Repair of Concrete (Depth equal to or less than 5 in.)

2 SF each



SILICONE BRIDGE JOINT SEALER DETAIL


(Depth equal to or less than 5 in.) 8 SF

Epoxy Crack Injection shall be per Section 590 of the IDOT Standard Specifications.

BILL OF MATERIAL

ITEM	UNIT	TOTAL
Structural Repair of Concrete (Depth equal to or less than 5 in.)	Sq. Ft.	13
Epoxy Crack Injection	Foot	28
Silicone Bridge Joint Sealer	Foot	12
Cleaning and Painting Steel Bridge	L. SUM	1
Containment and Disposal of Non-Lead Paint Cleaning Residues	L. SUM	1

<u>Scope of Work</u> Cleaning and Painting Steel, Expansion Joint Sealant, Concrete Repair, Epoxy Crack Injection



EXPANSION JOINT REPAIR



COLUMN REPAIR



CLEANING AND PAINTING STEEL

HRGreen

SOUTH FACE

SOUTH COLUMN

Epoxy Crack Injection —

USER NAME - whood	DESIGNED -	SLS	REVISED -
	CHECKED -	SLS	REVISED -
PLOT SCALE =	DRAWN -	WJH	REVISED -
PLOT DATE = 6/23/2022	CHECKED -	AEU	REVISED -

NORTH FACE

SOUTH COLUMN

CITY OF ROCKFORD

WEST FACE

NORTH COLUMN

вмо	HARRIS BANK CENTER PEDESTRIAN REPAIRS OVER CHRUCH STREET	BRIDGE
	SHEET NO. 1 OF 1 SHEETS	

F.A. RTE.	SECT	ΓΙΟΝ			COUNTY	TOTAL SHEETS	SHEE NO.
				1	WINNEBAGO	8	8
			CONTRACT	NO.			
numore see a				D. DDOJECT			